













**FORET POUR MACHINE MAGNETIQUE QUEUE WELDON  
BOREN VOOR MAGNEETBOORMACHINE WELDON SCHACHT  
DRILL FOR MAGNETIC MACHINE WELDON SHANK**

**HSS**

							
WELDON 19,05mm		WELDON 19,05mm		WELDON 19,05mm		WELDON 19,05mm	
<b>L</b>	<b>30 MM</b>	<b>L</b>	<b>30 MM</b>	<b>L</b>	<b>30 MM</b>	<b>L</b>	<b>30 MM</b>
<b>Dia</b>	<b>HSS</b> <b>ROT338W..</b>	<b>Dia</b>	<b>HSS</b> <b>ROT338W..</b>	<b>Dia</b>	<b>HSS</b> <b>ROT338W..</b>	<b>Dia</b>	<b>HSS</b> <b>ROT338W..</b>
6	06	11	11	17	17	24	24
8	08	12	12	18	18	27,5	275
8,5	085	13	13	19	19		
9	09	13,5	135	20	20		
9,5	095	14	14	21	21		
9,8	098	15	15	22	22		
10	10	16	16	23	23		

**DOUILLE WELDON 19,05 POUR FORET  
WELDON 19,05 HULS VOOR BOREN  
ADAPTER WELDON SHANK 19,05 FOR DRILL**



			
<b>Dia</b>	<b>RD2003/..</b>	<b>Dia</b>	<b>RD2003/..</b>
2,5	025	5	050
3	030	6	060
4	040	7	070
		8	080
		9	090
		10	100
		11	110
		12	120

**FORET A GRADINS POUR MACHINE MAGNETIQUE QUEUE WELDON  
TRAPBOREN VOOR MAGNEETBOORMACHINE WELDON SCHACHT  
STEP DRILL FOR MAGNETIC MACHINE WELDON SHANK**



WELDON 19,05mm	<b>D1</b>	<b>D2</b>	<b>D3</b>	<b>D4</b>	<b>D5</b>	<b>Hauteur D Hoogte D</b>	<b>HSS</b>
<b>ROTF0816</b>	8	10	12	14	16	12	
<b>ROTF1018</b>	10	12	14	16	18	12	
<b>ROTF2028</b>	20	22	24	26	28	12	
<b>ROTF3038</b>	30	32	34	36	38	12	
<b>ROTF4048</b>	40	42	44	46	48	12	
<b>ROTF1014</b>	10	12	14	-	-	25	
<b>ROTF1620</b>	16	18	20	-	-	25	
<b>ROTF2226</b>	22	24	26	-	-	25	
<b>ROTF2832</b>	28	30	32	-	-	25	
<b>ROTF3438</b>	34	36	38	-	-	25	
<b>ROTF4044</b>	40	42	44	-	-	25	
<b>ROTF4650</b>	46	48	50	-	-	25	