

**FRAISE CREUSE POUR MACHINE MAGNETIQUE QUEUE WELDON
 HOLLE FREZEN VOOR MAGNEETBOORMACHINE WELDON SCHACHT
 ANNULAR CUTTER FOR MAGNETIC MACHINE WELDON SHANK**

HSS - HSS-COBALT 5% - WELDON

L						L					
	30 MM	50 MM	30 MM	55 MM	110 MM		30 MM	50 MM	30 MM	55 MM	110 MM
Dia	HSS	HSS	HSS-CO	HSS-CO	COTIALN	Dia	HSS	HSS	HSS-CO	HSS-CO	COTIALN
	EC..	ECL..	ROTK..	ROTKL..	ROT.L100		EC..	ECL..	ROTK..	ROTKL..	ROT.L100
12	12	12	12	12		34	34	34	34	34	
12,5			125	125		35	35	35	35	35	35
13	13	13	13	13		36	36	36	36	36	36
13,5			135	135		37	37	37	37	37	
14	14	14	14	14		38	38	38	38	38	38
14,5			145	145		39	39	39	39	39	
15	15	15	15	15		40	40	40	40	40	40
15,5			155	155		41	41	41	41	41	
16	16	16	16	16		42	42	42	42	42	
16,5			165	165		43	43	43	43	43	
17	17	17	17	17		44	44	44	44	44	
17,5			175	175		45	45	45	45	45	45
18	18	18	18	18	18	46	46	46	46	46	
18,5			185	185		47	47	47	47	47	
19	19	19	19	19	19	48	48	48	48	48	
19,5			195	195		49	49	49	49	49	
20	20	20	20	20	20	50	50	50	50	50	50
20,5			205	205		51	51	51	51	51	
21	21	21	21	21	21	52	52	52	52	52	
21,5			215	215		53	53	53	53	53	
22	22	22	22	22	22	54	54	54	54	54	
22,5			225	225		55	55	55	55	55	
23	23	23	23	23	23	56	56	56	56	56	
23,5			235	235		57	57	57	57	57	
24	24	24	24	24	24	58	58	58	58	58	
24,5			245	245		59	59	59	59	59	
25	25	25	25	25	25	60	60	60	60	60	
25,5			255	255		61	61	61			
26	26	26	26	26	26	62	62	62			
26,5			265	265		63	63	63			
27	27	27	27	27	27	64	64	64			
27,5			275	275		65	65	65			
28	28	28	28	28	28	70			70	70	
28,5			285	285		75					
29	29	29	29	29	29	78	78				
29,5			295	295		80				80	
30	30	30	30	30	30	85		85	85		
30,5						90		90			
31	31	31	31	31		95					
32	32	32	32	32	32	100					
33	33	33	33	33	33	110					

	PILOTE - GELEIDER - EJECTOR PIN	ROTPI ROTPI/L ROTPI/LL ROTPI/LL2P	6,34x77	EC ROTK
			6,34x102	ECL ROTKL
			7,98x130	ROT..L100
			7,98x102	ROT..L100